





HST #837181627

DATE 2015-06-01	TECHNICIAN Darren Mann		JOB/ORDER # 4812	REFERENCE TEXT Client reference	
FIRST NAME Brenda		LAST NAME Thompson			
BILLING ADDRESS COMPANY / BILLING NAME 3086 ALBERTA ST VANCOUVER, V5Y3L9 BRITISH COLUMBIA, CANADA		9	SERVICE ADDRES 3086 ALBERTA ST VANCOUVER, V5Y BRITISH COLUMB		
PHONE 778.737.5887			EMAIL bren_kd@yahoo.co	om	

REASON FOR TODAY'S CALL:

-tub/shower on second floor won't fully shut off(older American Standard) -replace parts within tank of toilet in same bathroom.

DESCRIPTION OF WORK PERFORMED:

-Replaced the mixing and pressure balance cartridges in the second floor bathroom shower valve. -Replaced the toilet fillvalve, tilt valve gasket, and supply line in the same bathroom.

QTY.	CODE	DESCRIPTION			PRICE
1	//	Replace Mixing & Pressure Balance Cartridges - American Standard			\$189.00
1	//	Replace Toilet Fill-Valve, Tilt Valve Gasket, Supply line - ADD-ON PRICING			\$119.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				SUBTOTAL:	\$308.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$15.40
		s from your			\$323.40

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES, E. & O. E.

2015-06-01

CUSTOMER SIGNATURE