



DATE 2015-06-09	TECHNICIAN Darren Mann	JOB/ORDER # 4885	REFERENCE TEXT Client reference
FIRST NAME Ken		LAST NAME Waters	
BILLING ADDRESS COMPANY / BILLING NAME 889 HOMER ST. VANCOUVER, V6B 5S3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #2502 - 889 HOMER ST., BUZZER 253 VANCOUVER, V6B 5S3 BRITISH COLUMBIA, CANADA	
PHONE 604-833-7940		EMAIL kbw@hotmail.com	

REASON FOR TODAY'S CALL:  
issues with 2 shower arms

DESCRIPTION OF WORK PERFORMED:  
 ---Guest Bathroom: the threads of the shower arm broke off in the wall. I removed these broken threads and installed a new shower arm and standard head. ---  
 Master Bathroom: The shower head that is connected to the arm is leaking. It will have to be replaced.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Shower Head & Arm	\$119.00	\$119.00


**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL: \$119.00  
 GST (5%): \$5.95  
 TOTAL: \$124.95



2015-06-09

---

CUSTOMER SIGNATURE DATE