

Phone: 604.727.4484 yaletownplumbing.com

(E) @SimplyPlumbing f YaletownPlumbing

HST #837181627

| DATE 2015-06-10 | TECHNICIAN Darren Mann | | JOB/O 4891 | RDER # | REFERENCE TEXT Client reference |
|--|---------------------------|---------------------|--|-------------------------------|------------------------------------|
| FIRST NAME Jenn | | LAST NAME Kirker | 7 | | |
| BILLING ADDRESS COMPANY / BILLING NAME 3847 W 30TH AVE VANCOUVER, V6S 1W9 BRITISH COLUMBIA, CANADA | | 4 | SERVICE ADDRESS 3847 W 30TH AVE VANCOUVER, V6S 1W9 BRITISH COLUMBIA, CANADA | | |
| PHONE 6047621063 | | | | EMAIL jennkirker@gmail.com | |

REASON FOR TODAY'S CALL:

-replace Instant Hot Water unit under kitchen sink. -replace master bathroom lavatory mechanical drain(left sink).

DESCRIPTION OF WORK PERFORMED:

-Installed new instant hot water tank and filtration under kitchen sink. Tested. -Replaced mechanical lav pop-up in master bathroom(left sink). And tested by filling and draining multiple times.

| QTY . | CODE | DESCRIPTION | | PRICE |
|---|--|--|----------|----------|
| 1 | 1 | Install InSinkErator Hot Water Tank and Filtration System (HWT-F1000S) | \$499.00 | \$499.00 |
| 1 | 6 | Replace Lav Drain - Mechanical | \$159.00 | \$159.00 |
| Give us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY | | SUBTOTAL: | \$658.00 | |
| give us feel | LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF | GST (5%): | \$32.90 | |

Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.

Thank You!

| | 21 | \$153.00 | \$105.00 |
|---|---|------------------------------|----------|
| WARRANTY: | PARTS - SUBJECT TO MANUFACTURER'S WARRANTY | SUBTOTAL: | \$658.00 |
| | LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DA MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABS | | \$32.90 |
| | WARRANTY ON CUSTOMER SUPPLIED MATERIALS. | TOTAL: | \$690.90 |
| MATERIALS I SETTLED, RU RESULTING | | FOR BROKEN, ITHER DAMAGES | |
| | CUSTOMER SIGNATURE | DATE | |