



2015-06-10

DATE

HST #837181627

DATE 2015-06-10	TECHNICIAN Darren Mann		JOB/ORDER # 4896		REFERENCE TEXT Client reference	
FIRST NAME Alissa		LAST NAME Reem	9/			
BILLING ADDRESS COMPANY / BILLING NAME #1602 - 1483 HOMER ST BUZ# VANCOUVER, V6Z3C7 BRITISH COLUMBIA, CANADA	ING ADDRESS MPANY / BILLING NAME D2 - 1483 HOMER ST BUZ#1075 ICOUVER, V6Z3C7			#1602 - 1483 HOMER ST BUZ#1075 VANCOUVER, V6Z3C7 BRITISH COLUMBIA, CANADA		
PHONE 604.646.0561				EMAIL alissa.reem@gmail.com		

REASON FOR TODAY'S CALL:

-clean tub/shower drain master bathroom -tub in guest bathroom not used very often but seems to drain slow.

DESCRIPTION OF WORK PERFORMED:

I used the PowerSpin drain snake to clear hair from the master bathroom tub and shower(shared drain). Removed sludge from master lav drain. Removed hair from

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1	//	Clean drain using P	\$139.00	\$139.00	
e _m	e us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$139.00	
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$145.95
		we did.	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. IERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE