

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2015-06-26	TECHNICIAN Darren Mann		JOB/O 4949	RDER #	REFERENCE TEXT Client reference
FIRST NAME Dan		LAST NAME Boston	7		
BILLING ADDRESS			1.	SERVICE ADDRESS	
1 - 86 DALLAS ROAD VICTORIA, V8V1A2 BRITISH COLUMBIA, CANADA				705 - 989 BEATTY STREET YASUKA: 604.505.8152 BUZZER: 1705 VANCOUVER, V8Z 3C5 BRITISH COLUMBIA, CANADA	
PHONE 778.888.3076	2			EMAIL dbost101@gmail.com	

REASON FOR TODAY'S CALL:

Kitchen garborator has a slow leak... Water dripping under sink.

DESCRIPTION OF WORK PERFORMED:

The garburator was leaking from the mounting bracket and also through the unit. I replaced the garburator with new and tested by filling and draining the sink while running the garburator.

QTY.	CODE		DESCRIPTION		PRICE	
1	1.	Supply & Install 1/2H	Supply & Install 1/2HP Waste King 1001 Garburator			
Rena and Toodly ale WAR			ARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$279.00	
Give us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTE	GST (5%):	\$13.95	
		com/feedback [1] s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$292.95	
	tell us how v	d	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BA SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER D RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. <u>TERMS</u> : NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCH CHARGES. E. & O. E.	OKEN, AMAGES		
			2015-06-26	_		
			CUSTOMER SIGNATURE DATE			