



HST #837181627

DATE 2015-07-02	TECHNICIAN Darren Mann		JOB/ORDER # 4985	REFERENCE TEXT Client reference			
FIRST NAME dana		LAST NAME aljanaby					
BILLING ADDRESS COMPANY / BILLING NAME 409 - 822 SEYMOUR STREET VANCOUVER, V6B1L7 BRITISH COLUMBIA, CANADA		409 - 822 SEYMOU VANCOUVER, V6B	SERVICE ADDRESS  409 - 822 SEYMOUR STREET VANCOUVER, V6B1L7 BRITISH COLUMBIA, CANADA				
PHONE 604.312.2381			EMAIL daljanaby@hotmail.	com			

## REASON FOR TODAY'S CALL:

Garbarator broken. piece of glass stuck in it, motor stopped working and sink is leaking.

## **DESCRIPTION OF WORK PERFORMED:**

Installed customer supplied kitchen faucet. Tested by filling both sides of the sink and draining.

QTY.	CODE	DESCRIPTION			PRICE
1		Install Garburator - Cu	Install Garburator - Customer Supplied		
		and hack war	RRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$149.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$156.45
		J II	NTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY IADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

<u> Thank You!</u>

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES, E. & O. E.

2015-07-02

DATE

CUSTOMER SIGNATURE