



HST #837181627

DATE 2015-07-06	TECHNICIAN Darren Mann		JOB/O 4992	RDER#	REFERENCE TEXT Client reference	
FIRST NAME Judy		LAST NAME Sewell				
BILLING ADDRESS COMPANY / BILLING NAME 1501 - 1005 BEACH AVE BUZ# VANCOUVER, V6E3W2 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS  1501 - 1005 BEACH AVE BUTVANCOUVER, V6E3W2 BRITISH COLUMBIA, CANAL		
PHONE 604.687.6274 (home)				EMAIL judysewell@shaw.ca		

REASON FOR TODAY'S CALL: garburator leaking

## **DESCRIPTION OF WORK PERFORMED:**

The garburator was leaking right through the unit and out of the bottom. I replaced the garburator with new and tested by filling and draining the sink while running the garburator.

QTY.	CODE	DESCRIPTION				PRICE
1		Supply & Install 1/2HP Badger5 Garburator				\$299.00
Gwe us Feedback WARRANTY:		RANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY  LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$299.00	
Please visit our feedback page at:					GST (5%):	\$14.95
		TEREOT AT	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$313.95	
			THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND			

Thank You!

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2015-07-06 CUSTOMER SIGNATURE DATE