

Phone: 604.727.4484 yaletownplumbing.com

HST #837181627

DATE 2015-07-08	TECHNICIAN Darren Mann		JOB/ORDER # 4982	REFERENCE TEXT Client reference
FIRST NAME Mourad		LAST NAME Salji		
BILLING ADDRESS COMPANY / BILLING NAME 306 - 939 HOMER STREET VANCOUVER, V6B 2W6 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 306 - 939 HOMER ST VANCOUVER, V6B 2 BRITISH COLUMBIA	TREET, BUZZER 0731 PW6
PHONE 778.389.3186			EMAIL mourad@rightfoot.ca	

REASON FOR TODAY'S CALL:

"We have an under mounted sink that wasn't ideally installed. One of the supporting braces has broken and the other is pulling the wood support down. There is also a slight leak and drainage problem from one side of the sink."

DESCRIPTION OF WORK PERFORMED:

---I re-siliconed the lip of the kitchen sink and added L-brackets for extra support. ---I replaced the kitchen sink strainer assembly and tested by filling and draining both sides of the sink. ---I tightened a loose MJ band that was showing signs of leaking. ---I raised the dishwasher drain hose and supported to the back of the

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	//.	Quoted Price	\$289.00	\$289.00
<i>Q</i>	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			\$289.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$14.45
			TOTAL:	\$303.45
		WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED RUSTED DETERIORATION OR LEAD PIPES. SIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES.		

2015-07-08