

🕒 @SimplyPlumbing 🛛 🚹 YaletownPlumbing

HST #837181627

DATE 2015-07-15	TECHNICIAN Darren Mann		JOB/O 5028	RDER #	REFERENCE TEXT Client reference
FIRST NAME Daniel		LAST NAME Fu	7		
BILLING ADDRESS COMPANY / BILLING NAME 6279 EAGLES DRIVE VANCOUVER, V6T 2K7 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 201 - 6279 EAGLES DRIVE VANCOUVER, V6T 2K7 BRITISH COLUMBIA, CANADA	
PHONE 7789898690				EMAIL lookoverthere@gmail.com	

REASON FOR TODAY'S CALL:

Garburator broke down and that side of the sink is clogged. Want to see if it's fixable. If not, would prefer to remove it.

## DESCRIPTION OF WORK PERFORMED:

The garburator motor was burnt out. I removed the garburator, installed a basket strainer in its place, and re-piped the ABS drainage. Tested by filling and draining both sides of the sink.

<b>QTY.</b>	CODE		DESCRIPTION	UNIT PRICE	PRICE	
1		Delete Garburator	lete Garburator & Re-Pipe ABS Drainage			
Rung of Toodle al			WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$209.00	
<b>Give us Feedback</b> Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$10.45	
		.com/feedback [1]	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$219.45	
	t tell us how v		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALEATOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.			