

🕒 @SimplyPlumbing 🛛 🚹 YaletownPlumbing

HST #837181627

DATE 2015-07-22 TECHNICIAN Darren Mann JOB/ORDER # 5035 REFERENCE TEXT Client reference FIRST NAME LAST NAME	
	-
Caroline Jang	
BILLING ADDRESSSERVICE ADDRESSCOMPANY / BILLING NAME465 BEACH CRESCENT465 BEACH CRESCENT465 BEACH CRESCENTVANCOUVER, V6Z 3B9VANCOUVER, V6Z 3B9BRITISH COLUMBIA, CANADABRITISH COLUMBIA, CANADA	
PHONE EMAIL gang.caroline@gmail.com	n

REASON FOR TODAY'S CALL:

1. Shower head water pressure issue (maybe replacing the shower head?) 2. Toilet (slow filling toilet and getting clogged)

DESCRIPTION OF WORK PERFORMED:

-I replaced the Fillvalve in the powder room toilet. -The tub spout on the second floor is not functioning properly, allowing half of the water to flow through the spout when the shower is activated. I took pictures of the tub spout, parts will have to be ordered.

QTY.	CODE			UNIT PRICE	PRICE		
1		Replace toilet FillV	/alve - stand	ard	\$149.00	\$149.00	
0		and a sh	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$149.00
	t our feedbac	eedback		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.45	
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!				WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$156.45	
			SETTLED, R RESULTING	LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RES FUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS / FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. T CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATE E. & O. E. CUSTOMER SIGNATURE	AND ANY OTHER DAMAGES		