



2015-07-27 DATE

HST #837181627

DATE 2015-07-27	TECHNICIAN Darren Mann		JOB/ORDER # 5070		REFERENCE TEXT Client reference
FIRST NAME Steven		LAST NAME Ho			
BILLING ADDRESS COMPANY / BILLING NAME 788 HAMILTON ST, UNIT 801 VANCOUVER , V6B0E9 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS  801 - 788 HAMILTON ST BUZZER: 6059 VANCOUVER, V6B0E9 BRITISH COLUMBIA, CANADA	
PHONE 6046268367				EMAIL juststeven11@hotmail.com	

## REASON FOR TODAY'S CALL:

Sink stopper stuck deep in bathroom sink.

## DESCRIPTION OF WORK PERFORMED:

		seized up and could	not be repai	red. I replaced the pop-up drain assembly and tested by filling and draining	the sink multiple t	imes.
QTY.	CODE		DESCRIPTION			
1		Replace Pop-Up Lav drain - WO Overflow				\$169.00
<b>L</b> ma	, 115 G	oodkack	WARRANTY:	ARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$169.00
Gwe us Feedback  Please visit our feedback page at:  www.yaletownplumbing.com/feedback  Fill in the required details from your invoice and tell us how we did.  Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$8.45	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$177.45	
		MADE THAT MATERIALS SETTLED, RI RESULTING	T THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, USTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK  8. O. F.			

CUSTOMER SIGNATURE