

HST #837181627

| DATE 2015-07-27 | TECHNICIAN Darren Mann | | JOB/O 5071 | RDER # | REFERENCE TEXT Client reference |
|--|---------------------------|---------------------|---------------|--|------------------------------------|
| FIRST NAME Andrew | | LAST NAME Merkur | 7 | | |
| BILLING ADDRESS COMPANY / BILLING NAME 6061 ADERA STREET VANCOUVER, V6M 3J3 BRITISH COLUMBIA, CANADA | | | | SERVICE ADDRESS 6061 ADERA STREET VANCOUVER, V6M 3J3 BRITISH COLUMBIA, CANADA | |
| PHONE 7789987015 | | | | EMAIL amerkur@gmail.com | |

REASON FOR TODAY'S CALL:

"Mechanism to stop water when tank full is broken and water continuously flowing. Wasting water - no overflow. Just contant water filling sound"

DESCRIPTION OF WORK PERFORMED:

I replaced the toilet Fillvalve & supply line and tested.

| QTY. | CODE | | DESCRIPTION | UNIT PRICE | PRICE |
|---|------|----------------------|--|------------|----------|
| 1 | | Replace toilet FillV | \$169.00 | \$169.00 | |
| 0 | | and a du | WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY | SUBTOTAL: | \$169.00 |
| Guve us Jeedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You! | | | LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO | GST (5%): | \$8.45 |
| | | .com/feedback [1] | WARRANTY ON CUSTOMER SUPPLIED MATERIALS. | TOTAL: | \$177.45 |
| | | <u>u!</u> | MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2015-07-27 | | |
| | | | CUSTOMER SIGNATURE DATE | | |
| | | | | | |