



HST #837181627

DATE 2015-07-29	TECHNICIAN Darren Mann		JOB/ORDER # 5062		REFERENCE TEXT Client reference
FIRST NAME Ashley		LAST NAME Burke			
BILLING ADDRESS COMPANY / BILLING NAME 128 W CORDOVA ST VANCOUVER, V6B0E6 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS  2905 - 128 W CORDOVA ST ANGUS: 604.240.6187 BUZZER: 1254 VANCOUVER, V6B0E6 BRITISH COLUMBIA, CANADA	
PHONE 7782375552	-			EMAIL Abonnett22@gmail.com	

## REASON FOR TODAY'S CALL:

Toilet leaking \*Larry Bonnett 1.610.657.9989 Susan Bonnett 1.484.678.2991 Susanlbonnett@gmail.com

## DESCRIPTION OF WORK PERFORMED:

The leak was coming from a cracked plug in the tank. I contacted Caroma, ordered a replacement, installed the replacement and tested.

QTY.	CODE		DESCRIPTION			
1		Replace Plug In Ca	roma Tank	\$119.00	\$119.00	
Consus Goodles		Soud and	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$119.00	
Gwe us Feedback Please visit our feedback page at:	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.95			
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.  Thank You!			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$124.95	
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS. LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.			
			1 Distal			
			2015-07-29  CUSTOMER SIGNATURE DATE			