

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2015-07-30	TECHNICIAN Darren Mann		JOB/O 5078	RDER #	REFERENCE TEXT Client reference
FIRST NAME George		LAST NAME Pick	7		
BILLING ADDRESS COMPANY / BILLING NAME 1500 HORNBY VANCOUVER, V6Z2R1 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 608 - 1500 HORNBY BUZZER: #2126 VANCOUVER, V6Z2R1 BRITISH COLUMBIA, CANADA	
PHONE 604.961.0307	-			EMAIL pickgee@gmail.com	

REASON FOR TODAY'S CALL:

Toilet is not flushing properly. Seems to be a problem with tube not going back properly to stop the water.

DESCRIPTION OF WORK PERFORMED:

I replaced the FlushValve assembly and gasket.

QTY .	CODE		DESCRIPTION	UNIT PRICE	PRICE
1		Replace Kohler Flu	shValve Assembly	\$149.00	\$149.00
Current Goodle al			WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$149.00
Give us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$156.45
	t tell us how v		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		