



DATE 2015-08-04	TECHNICIAN Darren Mann	JOB/ORDER # 5093	REFERENCE TEXT Client reference
FIRST NAME Isabel		LAST NAME Portele	
BILLING ADDRESS EMR VACATION RENTALS 1118 RICHARDS ST VANCOUVER, V6B 3E6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1201 - 193 AQUARIUS MEWS CHARLES(TENANT): 604.620.4740 BUZZER: 1071 VANCOUVER, V6Z2Z2 BRITISH COLUMBIA, CANADA	
PHONE 604.628.0555		EMAIL isabel@emrvr.com	

REASON FOR TODAY'S CALL:
 Ensuite shower head is spraying water all around, even outside the shower door.

DESCRIPTION OF WORK PERFORMED:
 -The shower spray hose connector was broken. This was not original hardware, originally the shower head was of a standard type. I replaced this broken shower set up with a new Delta shower head and arm.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Shoer Head	\$119.00	\$119.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$119.00
GST (5%):	\$5.95
TOTAL:	\$124.95

_____ 2015-08-04
 CUSTOMER SIGNATURE DATE