

HST #837181627

DATE 2015-08-20	TECHNICIAN Darren Mann		JOB/ORDER # 5168	REFERENCE TEXT Client reference	
FIRST NAME Andrea		LAST NAME Banks			
BILLING ADDRESS COMPANY / BILLING NAME 499 BROUGHTON ST VANCOUVER, V6G3K1 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 302 - 499 BROUGHTON ST BUZZER: #1204 VANCOUVER, V6G3K1 BRITISH COLUMBIA, CANADA		
PHONE 7783719568			EMAIL Abanks916@gmail.cor	EMAIL Abanks916@gmail.com	

REASON FOR TODAY'S CALL:

Guest bathroom toilet gets clogged easily.

DESCRIPTION OF WORK PERFORMED:

-I ran the toilet auger through the toilet and did not run into any obstruction, the auger went through with ease. I believe the toilet just has a week flush. I will find possible replacement options.

TECHNICIAN RECOMMENDATIONS:

31.25" bottom of countertop to floor 12" rough in Elongated Comfort height if possible

QTY.	CODE	DESCRIPTION			PRICE
1		Labour		\$99.00	\$99.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				SUBTOTAL:	\$99.00
Please visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$4.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$103.95
		-	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

Thank You!

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

CUSTOMER SIGNATURE

DATE