

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2015-08-27	TECHNICIAN Darren Mann		JOB/OI 5210	RDER #	REFERENCE TEXT Client reference
FIRST NAME Gabriel		LAST NAME Zainescu	7		
BILLING ADDRESS COMPANY / BILLING NAME 12 - 11910 90 AVE DELTA, V4C3H6 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 1203 - 590 NICOLA ST GABRIEL DELTA, BRITISH COLUMBIA, CANADA	
PHONE 604.657.9108	-			EMAIL gzainescu@royalconcierge.ca	

REASON FOR TODAY'S CALL: Replace garburator

DESCRIPTION OF WORK PERFORMED:

-the garburator had a crack in the housing allowing water to seep out. I replaced the garburator with a new Waste King 1001 and tested by filling and draining the sink while running the garburator.

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1	Supply & Install 1/2HP Waste King 1001 Garburator				\$279.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		and hack	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$279.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$13.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$292.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FLYTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2015-08-27		
			CUSTOMER SIGNATURE DATE		
				·	