

2015-08-26

DATE

HST #837181627

DATE 2015-08-26	TECHNICIAN Darren Mann	War.	JOB/O 5199	RDER#	REFERENCE TEXT Client reference
FIRST NAME Lynden		LAST NAME Wei	97		
BILLING ADDRESS DUNOWEN PROPERTIES 201 - 1288 ALBERNI STREET VANCOUVER, V6E 4N5 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 1406 - 1288 ALBERNI VANCOUVER, V6E 4N5 BRITISH COLUMBIA, CANADA	4
PHONE 778.919.9810				EMAIL operations@dunowen.com	

REASON FOR TODAY'S CALL: Leaking garburator(Badger5)

DESCRIPTION OF WORK PERFORMED:

The garburator was cracked and leaking right through the unit. I replaced the garburator with a new Badger5 and tested by filling and draining the sink while running

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$299.00	\$299.00
<i>Q</i>	(1	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$299.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$14.95
			TOTAL:	\$313.95
		We did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED RUSTED DETERIORATION OR LEAD PIPES EXTURES. CLEAN QUITS AND ANY OTHER DAMAGES.		

CUSTOMER SIGNATURE