



HST #837181627

DATE 2015-08-28	TECHNICIAN Darren Mann		JOB/ORDER # 5207	REFERENCE TEXT Client reference
FIRST NAME Josh		LAST NAME Campbell		
BILLING ADDRESS COMPANY / BILLING NAME 933 SEYMOUR ST. VANCOUVER, V6B 6L6 BRITISH COLUMBIA, CANA			SERVICE ADDRESS 802 - 933 SEYMOUR BUZZER: 114 VANCOUVER, V6B 6 BRITISH COLUMBIA	ST.
PHONE 778-242-8253	-		EMAIL joshua_campbell@me	e.com

REASON FOR TODAY'S CALL:

Clogged bathtub drain. Water fills the tub and takes a few hours to drain.

DESCRIPTION OF WORK PERFORMED:

I used the PowerSpin drain snake to clear hair from the tub drain. Tested by filling the tub 6" and draining.

QTY.	CODE	DESCRIPTION			UNIT PRICE	PRICE
1		Clean drain using Pow	Clean drain using PowerSpin / Tub/Shower			\$139.00
Gwe us Feedback WARRANTY:			ARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00
	Please visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$145.95	
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND				

Thank You!

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CUSTOMER SIGNATURE

2015-08-28 DATE