

HST #837181627

DATE 2015-09-04	TECHNICIAN Darren Mann		JOB/ORDER # 5228	REFERENCE TEXT Client reference	
FIRST NAME Linda		LAST NAME Lund			
BILLING ADDRESS COMPANY / BILLING 901 - 977 MAINLAND VANCOUVER, V6B1T BRITISH COLUMBIA,	ST 2		SERVICE ADDRESS 901 - 977 MAINLAND VANCOUVER, V6B1' BRITISH COLUMBIA	9 ST, BUZZER 7069 T2	
PHONE 604.689.7921			EMAIL lindaplund@telus.net		

REASON FOR TODAY'S CALL:

Remove garburator

DESCRIPTION OF WORK PERFORMED:

-I removed the garburator, installed a basket strainer in its place, and re-piped the ABS drainage. Tested by filling both sides of the sink and draining. -I also installed a customer supplied replacement shower cartridge.

QTY.	CODE	DESCRIPTION			PRICE
1		Delete Garburator & Re-Pipe ABS Drainage			\$199.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		warra	: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$199.00
				GST (5%):	\$9.95
		ls from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$208.95

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2015-09-04

CUSTOMER SIGNATURE

DATE