

(a) @SimplyPlumbing **F** YaletownPlumbing

HST #837181627

DATE 2015-09-09	TECHNICIAN Darren Mann		JOB/ORDER # 5251		REFERENCE TEXT Client reference
FIRST NAME Priyanka		LAST NAME Halli	7		
BILLING ADDRESS COMPANY / BILLING NAME 1255 SEYMOUR ST VANCOUVER , V6B0H1 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS #1004 - 1255 SEYMOUR ST VANCOUVER , V6B0H1 BRITISH COLUMBIA, CANADA	
PHONE 7789289921				EMAIL Priyankah@yahoo.com	

REASON FOR TODAY'S CALL: Garburator jammed

DESCRIPTION OF WORK PERFORMED:

-I managed to free up the grinding chamber but the garburator was not operating as normal. Pieces of the grinding chamber had rusted and flaked off and the spinning wheel at the base of the chamber was warped causing it to rub on the side walls when in use. I replaced the Garburator with new and tested by filling and draining the sink while running the garburator.

QTY .	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1		Supply & Install 1/2	ly & Install 1/2HP Badger5 Garburator				
Run of Toodle al				PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAY MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABS WARRANTY ON CUSTOMER SUPPLIED MATERIALS. T THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMEN		SUBTOTAL:	\$299.00
Guve us Geedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		GST (5%):				\$14.95	
					TOTAL:	\$313.95	
		SETTLED, RU RESULTING	LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESP JJSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AI FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. "CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATEF : & O. E. CUSTOMER SIGNATURE				