

(E) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2015-09-10	TECHNICIAN Darren Mann		JOB/OI 5255	RDER #	REFERENCE TEXT Client reference
FIRST NAME Simon		LAST NAME Cairns	7		
BILLING ADDRESS COMPANY / BILLING NAME 1506 - 1201 MARINASIDE CRE VANCOUVER, V6Z 2V2 BRITISH COLUMBIA, CANADA		\sim	4	SERVICE ADDRESS 1506 - 1201 MARINASIDE CRE BUZZER: 171 VANCOUVER, V6Z 2V2 BRITISH COLUMBIA, CANADA	
PHONE 778.996.6415				EMAIL yaletownkid@gmail.com	

REASON FOR TODAY'S CALL:

Master bathroom tub clog. *call phone, buzzer not working great.

DESCRIPTION OF WORK PERFORMED:

When I arrived onsite the tub overflow cover had been removed and Simon mentioned that he had removed a small clump of hair but the tub still was not draining. Simon also mentioned that when the lavatory sink was used water would back up into the tub. I ran the PowerSpin drain snake through the lavatory sink drain, removed a large clump of hair, and tested by filling both the Lav sink and the tub(8"), and draining both.

QTY. CODE	DESCRIPTION	UNIT PRICE	PRICE
1	Clean drain using PowerSpin / Tub/Shower	\$139.00	\$139.00
Q	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00
Give us Feedback Please visit our feedback page at:	LABOUR - 1 YEAR ON NEW UNITS 30 DAYS ON REPAIR VOID AFTER 30 DAYS IF	GST (5%):	\$6.95
www.yaletownplumbing Fill in the required detail		TOTAL:	\$145.95
invoice and tell us how the second se	MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		