



DATE 2015-09-14	TECHNICIAN Darren Mann	JOB/ORDER # 5267	REFERENCE TEXT Client reference
FIRST NAME Florence		LAST NAME Chan	
BILLING ADDRESS VANCOUVER RENT IT / COLDWELL BANKER PRESTIGE REALTY 310 - 638 BROUGHTON ST VANCOUVER, V6G3K3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 604 - 1205 HOWE ST BUZ#1715 PARKER: 604.649.3309 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.836.7368		EMAIL Flo@vancouverrentit.com	

REASON FOR TODAY'S CALL:
Leak under kitchen sink

DESCRIPTION OF WORK PERFORMED:
The leak was coming from a crack in the garburator drain 90. I replaced this 90 and the ABS drainage as it was glued to the cracked 90. Tested by filling and draining the sink while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Garb Drain 90	\$139.00	\$139.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$139.00
GST (5%):	\$6.95
TOTAL:	\$145.95

_____ 2015-09-14

 CUSTOMER SIGNATURE DATE