

(B) @SimplyPlumbing | | YaletownPlumbing



HST #837181627

DATE 2015-09-24	TECHNICIAN Darren Mann		JOB/ORDER # 5322		REFERENCE TEXT Client reference
FIRST NAME Aida		LAST NAME Hakirevic			
BILLING ADDRESS COMPANY / BILLING NAME 3008 W 4TH AVE. VANCOUVER, V6K1R4 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 3008 W 4TH AVE. APOSTOLOS(TENANT): 604-41 VANCOUVER, V6K1R4 BRITISH COLUMBIA, CANADA	
PHONE 6043752580				EMAIL a.hakirevic@gmail.com	

## REASON FOR TODAY'S CALL:

Leaky toilet - looks like the flapper isn't functioning properly and is preventing the tank from filling up. Tenant will be onsite.

## DESCRIPTION OF WORK PERFORMED:

-The toilet flapper was warped allowing water to constantly trickle from the tank to the bowl, I replaced this flapper and during testing notice that the fillvalve was struggling to turn the flow of water off once the tank was full. I replaced the fillvalve and supply line, tested again and in good working order.

QTY.	CODE		UNIT PRICE	PRICE	
1		Replace Toilet Fill-Valve, 3" Flapper, Supply			\$179.00
0		SUBTOTAL:	\$179.00		
Gwe us Feedback  Please visit our feedback page at:  www.yaletownplumbing.com/feedback  Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$8.95
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  ST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$187.95
Thank You!			HAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND IALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, ID, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES ING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK ES. E. & O. E.		

CUSTOMER SIGNATURE

DATE