



HST #837181627

DATE 2015-10-08	TECHNICIAN Darren Mann		JOB/ORDER # 5376	REFERENCE TEXT Client reference	
FIRST NAME Lauren		LAST NAME Kent			
BILLING ADDRESS COMPANY / BILLING NAME 989 BEATTY STREET VANCOUVER, V6Z 3C2 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 601 - 989 BEATTY STREET BUZZER: CALL604-671-6115 VANCOUVER, V6Z 3C2 BRITISH COLUMBIA, CANADA		
PHONE 604-671-6115			EMAIL lauren@laurenkent.ca	EMAIL lauren@laurenkent.ca	

REASON FOR TODAY'S CALL: delete garburator.

DESCRIPTION OF WORK PERFORMED:

-I remove the garburator, installed a basket strainer in its place, and re-piped the abs drainage. Tested by filling and draining the sink.

QTY.	CODE	DESCRIPTION			PRICE
1	1	Delete Garburator & Re-	ete Garburator & Re-Pipe ABS Drainage		\$199.00
0	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$199.00	
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		\$9.95
		ls from your			\$208.95
invoice and tell us how we did.			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

Thank You!

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

