



DATE 2015-10-13	TECHNICIAN Darren Mann	JOB/ORDER # 5390	REFERENCE TEXT Client reference
FIRST NAME Sue & Bruno		LAST NAME Lindenblatt	
BILLING ADDRESS COMPANY / BILLING NAME #1802 - 1501 HOWE ST BUZ#8065 VANCOUVER, BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #1802 - 1501 HOWE ST BUZ#8065 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.408.4493		EMAIL s.scholton@yahoo.com	

REASON FOR TODAY'S CALL:
Lavatory sink draining slowly.

DESCRIPTION OF WORK PERFORMED:
-I cleared hair from the top of the master bathroom lavatory sink drain(right sink). -I tightened the guest bathroom toilet seat but could not tighten the master bathroom toilet seat because the bolts were rusted.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$99.00	\$99.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2015-10-13

[Handwritten Signature]

CUSTOMER SIGNATURE DATE

SUBTOTAL:	\$99.00
GST (5%):	\$4.95
TOTAL:	\$103.95