



HST #837181627

DATE 2015-10-15	TECHNICIAN Darren Mann		JOB/ORDER # 5394		REFERENCE TEXT Client reference				
FIRST NAME Easyrent		LAST NAME Admin							
BILLING ADDRESS EASYRENT REAL ESTATE SERVICES LTD. 100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 2501 - 610 GRANVILLE ST BUZ#5321 LEV(TENANT): 604.582.6677 / 604.782.1694 VANCOUVER, BRITISH COLUMBIA, CANADA					
PHONE 604.662.3279				EMAIL info@easyrent.ca					

REASON FOR TODAY'S CALL: garburator jammed *call when en route

DESCRIPTION OF WORK PERFORMED:

The inside of the grinding chamber had deteriorated to the point where chunks of metal were breaking off. I replaced the garburator and tested by filing and draining the sink while running the garburator.

QTY.	CODE	DESCRIPTION			PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator			\$279.00
Come us Goodlade			WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$279.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$13.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$292.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE