



HST #837181627

DATE 2015-10-20	TECHNICIAN Darren Mann		JOB/ORDER # 5406		REFERENCE TEXT Client reference
FIRST NAME warda		LAST NAME toma	9/		
BILLING ADDRESS COMPANY / BILLING NAME 1625 MANITOBA STREET VANCOUVER, V5Y0B8 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 405 - 1625 MANITOBA STREET BUZZER: 4405 VANCOUVER, V5Y0B8 BRITISH COLUMBIA, CANADA	
PHONE 6043458662				EMAIL warda.toma@gmail.com	

REASON FOR TODAY'S CALL:

"I have a Kohler Saile toilet that is very noisy and makes a very loud filling noise every few minutes. It is also quite loud as the water fills when the toilet is flushed."

DESCRIPTION OF WORK PERFORMED:

I replaced the flushvalve gasket and tested.

QTY.	CODE	DESCRIPTION				PRICE
1		Replace FlushValv	ve Gasket		\$109.00	\$109.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.		WARRANTY:	<u>PARTS</u> - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.00	
		,	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.45	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$114.45	
		MADE THAT MATERIALS SETTLED, R	IT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, USTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.			

Thank You!

CHARGES, E. & O. E.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2015-10-20

CUSTOMER SIGNATURE

DATE