

(B) @SimplyPlumbing | YaletownPlumbing

HST #837181627

DATE 2015-10-20	TECHNICIAN Darren Mann		JOB/ORDER # 5431		REFERENCE TEXT Client reference
FIRST NAME Mary Jane		LAST NAME Brown	97		
BILLING ADDRESS COMPANY / BILLING NAME 3838 WEST 1ST AVE VANCOUVER, V6R1H5 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS  3838 WEST 1ST AVE VANCOUVER, V6R1H5 BRITISH COLUMBIA, CANADA	ı.
PHONE 604.762.6170				EMAIL mjbrown@erythana.com	

## REASON FOR TODAY'S CALL:

Toilet in basement is leaking from the back- either between the wall & the tank or the connection into the tank. 11 year-old toilet so can probably use a new inside rubber flapper too.

## DESCRIPTION OF WORK PERFORMED:

QTY.	CODE		DESCRIPTION			
1		Replace Toilet Fill-Valve, Flapper, Supply - S	\$169.00	\$169.00		
<b>L</b> mo	, 115 G	warranty: Parts - Subje	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	UBTOTAL:	\$169.00	
Gwe us Feedback Please visit our feedback page at:		c page at:	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO			
www.yaletownplumbing.com/feedback [1] Fill in the required details from your		COM/Teedback [1]	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$177.45	
invoice and tell us how we did.		INTEREST AT THE LEGAL RATE MADE THAT SERVICES LISTED MATERIALS LISTED HEREON A SETTLED, RUSTED, DETERIOR RESULTING FROM CLEANING (	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK			

2015-10-20

CUSTOMER SIGNATURE

DATE