



DATE 2015-10-22	TECHNICIAN Darren Mann	JOB/ORDER # 5435	REFERENCE TEXT Client reference
FIRST NAME Harley		LAST NAME Sinclair	
BILLING ADDRESS COMPANY / BILLING NAME 590 NICOLA STREET VANCOUVER, V6G3J8 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1403 - 590 NICOLA STREET BUZZER: 1068 VANCOUVER, V6G3J8 BRITISH COLUMBIA, CANADA	
PHONE 604-803-9541		EMAIL harleysinclair@shaw.ca	

REASON FOR TODAY'S CALL:
Leak between the sink and the garburator. (waste King)

DESCRIPTION OF WORK PERFORMED:
The garburator was leaking and the inside of the grinding chamber was very rusty. I replaced the garburator and tested by filling and draining the sink while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$279.00
GST (5%):	\$13.95
TOTAL:	\$292.95

_____ 2015-10-22

 CUSTOMER SIGNATURE DATE