

HST #837181627

DATE 2015-10-29	TECHNICIAN Darren Mann		JOB/ORDER # 5411		REFERENCE TEXT Client reference
FIRST NAME George		LAST NAME Pick			
BILLING ADDRESS COMPANY / BILLING NAME 1500 HORNBY VANCOUVER, V6Z2R1 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 608 - 1500 HORNBY BUZZER: #2126 VANCOUVER, V6Z2R1 BRITISH COLUMBIA, CANADA	
PHONE 604.961.0307				EMAIL pickgee@gmail.com	

REASON FOR TODAY'S CALL:

The detachable shower hose holder has snapped off, so it can't hang from the shower wall anymore.

DESCRIPTION OF WORK PERFORMED:

I replaced the shower head holder with new.

QTY.	CODE	DESCRIPTION			PRICE
1	//	Labour		\$99.00	\$99.00
1	//	SHWR Wall Bracket		\$25.00	\$25.00
Gwe us Feedback			WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		\$124.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.20
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. EREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$130.20
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

Thank You!

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. $\underline{\textbf{TERMS}}\text{: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK}$ CHARGES, E. & O. E.

2015-10-29
DATE