



2015-10-30

DATE

HST #837181627

DATE 2015-10-30	TECHNICIAN Darren Mann		JOB/ORDER # 5460	REFERENCE TEXT Client reference	
FIRST NAME richard		LAST NAME wittstock			
BILLING ADDRESS COMPANY / BILLING NAME 3211 WEST 2ND AVENUE VANCOUVER, V6K1K9 BRITISH COLUMBIA, CANADA		19	SERVICE ADDRES 2805 - 438 SEYMO VANCOUVER, V6K BRITISH COLUMB	UR ST (1K9	
PHONE 604 3199400			EMAIL rwittstock@shaw.ca	a	

## REASON FOR TODAY'S CALL:

Something wrong with toilet filler valve - tank doesn't fill properly. Nothing wrong with water valve, problem is at the toilet.

## DESCRIPTION OF WORK PERFORMED:

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1		Replace FillValve &	ve & Supply Line - Standard		\$159.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.  Thank You!		and a clay	VARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00
			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$166.95
		we did.	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE