



HST #837181627

DATE 2015-10-27	TECHNICIAN Darren Mann		JOB/ORDER # 5410	REFERENCE TEXT Client reference	
FIRST NAME Brad		LAST NAME Nykyforiak			
BILLING ADDRESS COMPANY / BILLING NAME 417 - 221 UNION STREET VANCOUVER, V6A 0B4 BRITISH COLUMBIA, CANADA		417 - 221 UNION S SASHA(TENANT): VANCOUVER, V6A	SERVICE ADDRESS 417 - 221 UNION STREET, BUZZER 1528 SASHA(TENANT): 778.875.3307 VANCOUVER, V6A 0B4 BRITISH COLUMBIA, CANADA		
PHONE 778.846.3339		EMAIL brad_nykyforiak@h	EMAIL brad_nykyforiak@hotmail.com		

REASON FOR TODAY'S CALL:

Garburator jammed.(was unjammed July21)

DESCRIPTION OF WORK PERFORMED:

I removed 2 pieces of glass from the grinding chamber and tested. The garburator seemed to be in good working order but Brad decided to replace it with new. I replaced with a new Waste King 1001 and tested by filling and draining the sink while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	/	Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00
<i>Q.q</i>	(1	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANT	SUBTOTAL:	\$279.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REP		\$13.95
			TOTAL:	\$292.95
		We did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLE MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING SETTLED RUSTED DETERIORATION OR LEAD PIPES FIXTURES CI	ETED AND THAT CHARGES AND IS NOT RESPONSIBLE FOR BROKEN, LEAN OUTS AND ANY OTHER DAMAGES R PIPING.	

CUSTOMER SIGNATURE

DATE