

HST #837181627

DATE 2015-11-09	TECHNICIAN Darren Mann		JOB/ORDER # 5494	REFERENCE TEXT Client reference	
FIRST NAME Sasha		LAST NAME Walshe			
BILLING ADDRESS COMPANY / BILLING NAME 503 - 531 BEATTY ST VANCOUVER, V6B 0C5 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS  503 - 531 BEATTY ST VANCOUVER, V6B 0C5 BRITISH COLUMBIA, CANADA		
PHONE 778.773.8530			EMAIL sasha.walshe@xerox.	com	

## REASON FOR TODAY'S CALL:

can hear pipes in bathroom gurgling. Does not appear to be any blockage. Sometimes when I flush toilet I can hear the bath tub pipes gurgle. Gurgling is intermittent Buz#553

## DESCRIPTION OF WORK PERFORMED:

I used the PowerSpin drain snake to clear hair and floss from the tub & lavatory drains. Tested by filling and draining the tub and lavatory.

## TECHNICIAN RECOMMENDATIONS:

When trying to re-attach the lavatory drain stopper the threads snapped off.

QTY.	CODE	DESCRIPTION			UNIT PRICE	PRICE
1	11	Clean drain using PowerSpin / Tub/Shower			\$139.00	\$139.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				SUBTOTAL:	\$139.00	
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		\$6.95	
		WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY		TOTAL:	\$145.95	
		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND				

Thank You!

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

