



HST #837181627

DATE 2015-11-13	TECHNICIAN Darren Mann		JOB/ORDER # 5518	REFERENCE TEXT Client reference	
FIRST NAME James		LAST NAME Millar			
BILLING ADDRESS N/A 804-1127 BARCLAY ST VANCOUVER, V6E4C6 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 804 - 1127 BARCLAY ST BUZ 18 VANCOUVER, V6E4C6 BRITISH COLUMBIA, CANADA		
PHONE 6047898342			EMAIL jimmillar@shaw.ca		

REASON FOR TODAY'S CALL:

The drain under my bathroom sink is beginning to back up. I think the problem is further down the drain near the wall. It needs to be routed. This problem happened about 13 years ago as well. The drain was routed and has been good until now.

DESCRIPTION OF WORK PERFORMED:

I cleaned the lavatory drain using the PowerSpin drain snake and tested by filling and draining the sink multiple times. There was an open portion of drainage under the lavatory sink where the dryer condensation hose drains into. I used a dishwasher drain coupling to secure the condensation hose to the drain.

QTY.	CODE	DESCRIPTION			PRICE
1		Clean drain using PowerSpin / Lavatory			\$139.00
1		Dishwasher Drain Coupling			\$10.00
www.yaletownplumbing.com/feedback [1] WARRANTY ON CUSTOMER SUPPLIED MATERIALS. Fill in the required details from your		SUBTOTAL:	\$149.00		
				GST (5%):	\$7.45
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		\$156.45

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

2015-11-13

DATE

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CUSTOMER SIGNATURE