

HST #837181627

DATE 2015-11-24	TECHNICIAN Darren Mann		JOB/OI 5544	RDER #	REFERENCE TEXT Client reference	
FIRST NAME Nancy		LAST NAME Temple	707			
BILLING ADDRESS COMPANY / BILLING NAME #1106 - 120 MILROS AVE BUZ#067 VANCOUVER, V6A4K7 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS #1106 - 120 MILROS AVE BU VANCOUVER, V6A4K7 BRITISH COLUMBIA, CANAD		
PHONE 604.899.4035				EMAIL templedn@gmail.com		

REASON FOR TODAY'S CALL: Mechanical lav drain broken.

DESCRIPTION OF WORK PERFORMED:

I replaced the mechanical lav drain in the master bathroom sink. Tested by filling and draining multiple times.

QTY.	CODE		UNIT PRICE	PRICE	
1	17/	Replace Lav Drain -	Mechanical	\$159.00	\$159.00
<i>Q</i>		and a di v	VARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$166.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

2015-11-24

DATE