





2015-11-26

DATE

HST #837181627

DATE 2015-11-26	TECHNICIAN Darren Mann		JOB/O 5567	RDER #	REFERENCE TEXT Client reference
FIRST NAME Lynden		LAST NAME Wei			
BILLING ADDRESS DUNOWEN PROPERTIES 201 - 1288 ALBERNI STREET VANCOUVER, V6E 4N5 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS 1402 - 1200 WEST GEORGIA VANCOUVER, V6E 4R2 BRITISH COLUMBIA, CANADA	
PHONE 778.919.9810				EMAIL operations@dunowen.com	

REASON FOR TODAY'S CALL:

Client reported shower pressure is low to the point the shower is not usable.

DESCRIPTION OF WORK PERFORMED:

I removed the shower valve cartridge and noticed quite a bit of debris in the hot side inlet to the faucet. I flushed the debris out, re-installed the cartridge & trim, and

QTY.	CODE	DESCRIPTION			PRICE
1		Labour		\$99.00	\$99.00
<i>Q.a</i>	(1	and lack	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$99.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$4.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$103.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE