



HST #837181627

DATE 2015-11-26	TECHNICIAN Darren Mann		JOB/O 5577	RDER #	REFERENCE TEXT
FIRST NAME Lynden		LAST NAME Wei			
BILLING ADDRESS DUNOWEN PROPERTIES 201 - 1288 ALBERNI STREET VANCOUVER, V6E 4N5 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS 2902 - 1200 ALBERNI ST VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.919.9810				EMAIL operations@dunowen.com	

REASON FOR TODAY'S CALL:

Tub drain backing up.

DESCRIPTION OF WORK PERFORMED:

I used the PowerSpin drain snake to remove hair from the master bathroom tub drain. The guest bathroom tub drain had no hair in it. Tested and both draining well.

TECHNICIAN RECOMMENDATIONS:

While onsite the tenant mentioned that the toilet in the master bathroom was taking a long time to refil after each flush. The fillvalve will have to be replaced to rectify this issue.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Clean drain using PowerSpin / Tub/Shower	\$139.00	\$139.00
WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				\$139.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$6.95
			TOTAL:	\$145.95

<u>Thank You!</u>

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTIES THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLIMATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBIN SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CRESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES STERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR L	LETED AND THAT CHARGES AND G IS NOT RESPONSIBLE FOR BROKEN, CLEAN OUTS AND ANY OTHER DAMAGES OR PIPING.
CHARGES. E. & O. E.	
	2015-11-26
CUSTOMER SIGNATURE	DATE