

HST #837181627

DATE 2015-12-01	TECHNICIAN Darren Mann		JOB/ORDER # 5572	REFERENCE TEXT Client reference	
FIRST NAME Paul		LAST NAME Alfonso		·	
BILLING ADDRESS COMPANY / BILLING NAME 888 HOMER ST VANCOUVER, V6B0H7 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 2604 - 888 HOMER ST BUZZER: 0920 VANCOUVER, V6B0H7 BRITISH COLUMBIA, CANADA		
PHONE 6046528689			EMAIL madebykimberly@gma	il.com	

REASON FOR TODAY'S CALL:

Toilet water does not fill up right away in the tank like before. It takes long time to fill up and it makes water sound for a long time after each flush. It's been like this for past 4 days.

DESCRIPTION OF WORK PERFORMED:

I replaced the toilet fillvalve and supply line.

QTY.	CODE	DESCRIPTION			UNIT PRICE	PRICE
1		Replace toilet FillValve - standard			\$149.00	\$149.00
invoice and tell us how we did.		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$149.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.45	
		INTEREST AT	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$156.45	
			SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,			

<u>Thank You!</u>

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. CUSTOMER SIGNATURE DATE