



DATE 2015-12-03	TECHNICIAN Darren Mann	JOB/ORDER # 5578	REFERENCE TEXT Client reference
FIRST NAME Andrew		LAST NAME Storrs	
BILLING ADDRESS COMPANY / BILLING NAME 1008 CAMBIE ST. VANCOUVER, V6B 6J7 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2808 - 1008 CAMBIE ST. BUZZER: 5213 VANCOUVER, V6B 6J7 BRITISH COLUMBIA, CANADA	
PHONE 7787729711		EMAIL yaletownplumbing@acsm.me	

REASON FOR TODAY'S CALL:
 Garburator disposal is broken, not your usual jam (I can clear those) - it looks more like the bearing/shaft on the motor cracked (the flywheel appears to wobble side-to-side when touched). Likely needs to be replaced.

DESCRIPTION OF WORK PERFORMED:
 I replaced the garburator and tested by filling and draining both sides of the sink while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2015-12-03

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$279.00
GST (5%):	\$13.95
TOTAL:	\$292.95