

(B) @SimplyPlumbing | | YaletownPlumbing



HST #837181627

DATE 2015-12-07	TECHNICIAN Darren Mann		JOB/ORDER # 5587	REFERENCE TEXT Client reference
FIRST NAME Nathan		LAST NAME Kim		·
BILLING ADDRESS COMPANY / BILLING NAME 1804 - 1200 WEST GEORGIA ST VANCOUVER, V6E4R2 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS  1804 - 1200 WEST GEORGIA STREET BUZZER: 1840 VANCOUVER, V6E4R2 BRITISH COLUMBIA, CANADA	
PHONE 604.365.6653		EMAIL nate.nkim@gmail.co	EMAIL nate.nkim@gmail.com	

## REASON FOR TODAY'S CALL:

Broken garburator. Tried flicking the reset switch but that doesn't work either. Garburator pipes connected to dishwasher, so dishwasher is using dirty water.

## DESCRIPTION OF WORK PERFORMED:

-I replaced the garburator with new and tested by filling and draining the sink while running the garburator. I also ran the dishwasher through a drain cycle to empty the standing water.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00
0	(1	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$279.00
Gwe us Feedback  Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.  Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$13.95
			TOTAL:	\$292.95
		WE did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND  MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,  SETTLED RUSTED DETERIORATION OR LEAD PIPES. SIXTURES OF EAN OUTS AND ANY OTHER DAMAGES.		

CUSTOMER SIGNATURE

DATE