



HST #837181627

DATE 2015-12-08	TECHNICIAN Darren Mann		JOB/ORDER # 5609	REFERENCE TEXT Client reference		
FIRST NAME Menny		LAST NAME Marangoudakis				
BILLING ADDRESS COMPANY / BILLING NAME 2601-1188 PENDER STREET WEST VANCOUVER, V6E0A2 BRITISH COLUMBIA, CANADA			2601 - 1188 PENDE VANCOUVER, V6E	SERVICE ADDRESS 2601 - 1188 PENDER ST, BUZZER 2601 VANCOUVER, V6E0A2 BRITISH COLUMBIA, CANADA		
PHONE 6046838448			EMAIL menny@live.ca			

REASON FOR TODAY'S CALL:

Thank You!

Garburator is cracking up and needs to be replaced. Everything is in good condition, this is a new 5 year old building.

DESCRIPTION OF WORK PERFORMED:

The garburator had cracks in the housing allowing water to leak through. I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE		DESCRIPTION			PRICE
1	//	Supply & Install 1/2	y & Install 1/2HP Badger5 Garburator			\$299.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$299.00	
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$14.95		
		WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		TOTAL:	\$313.95	
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.				

CUSTOMER SIGNATURE

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2015-12-08

DATE