

Phone: 604.727.4484 yaletownplumbing.com



2015-12-08

DATE

HST #837181627

DATE 2015-12-08	TECHNICIAN Darren Mann		JOB/ORDER # 5611		REFERENCE TEXT Client reference
FIRST NAME Maarten		LAST NAME Koorn			
BILLING ADDRESS COMPANY / BILLING NAME SUITE 210 - 24 4TH AVENUE EAST VANCOUVER, V5T 1E8 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS  1908 - 969 RICHARDS STREET NICOLE(TENANT): 778.317.2558. BUZZER: 1958 VANCOUVER, V6B 1A8 BRITISH COLUMBIA, CANADA	
PHONE 1.604.250.0212				EMAIL maartenk@ngc.build	

REASON FOR TODAY'S CALL: garburator jammed

## DESCRIPTION OF WORK PERFORMED:

The grinding chamber was deteriorating to the point where chunks of metal were flaking off. I replaced the garburator with new and tested by filling and draining the sink while running the garburator.

## TECHNICIAN RECOMMENDATIONS:

During testing I noticed the kitchen faucet has a very small leak coming from within the body of the faucet when in use and a small amount of water is making its way to the underside of the sink. The tenant has a bowl under the sink collecting the drips for now but the faucet should be replaced.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE	
1	11 (-	Supply & Install 1/2HP Waste King 1001 Garburator			
Give us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				\$279.00	
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.  Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$13.95	
			TOTAL:	\$292.95	
		WE did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND  MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,  SETTLED PLISTED DETERIORATION OF LEAD PIPES SIXTURES CLEAN OUTS AND ANY OTHER DAMAGES.			

CUSTOMER SIGNATURE