



DATE 2015-12-14	TECHNICIAN Darren Mann	JOB/ORDER # 5614	REFERENCE TEXT Client reference
FIRST NAME Brenda		LAST NAME Chong	
BILLING ADDRESS COMPANY / BILLING NAME 833 HOMER VANCOUVER, V6B 0H4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #2902 - 833 HOMER VANCOUVER, V6B 0H4 BRITISH COLUMBIA, CANADA	
PHONE 778.822.2846		EMAIL shingchong@yahoo.com	

REASON FOR TODAY'S CALL:

-I was told that a piece of plastic inside holds the stainless steel cover attached to the tile walls. That plastic is no longer working and that is why there is a white border at the top and the cover falls down a bit. -re-silicone around base of shower

DESCRIPTION OF WORK PERFORMED:

-I re-siliconed around the base of the shower. -I used silicone to resecure the shower valve trim.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Re-silicone Shower	\$139.00	\$139.00


Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:		\$139.00
GST (5%):		\$6.95
TOTAL:		\$145.95

 <hr/> CUSTOMER SIGNATURE	2015-12-14 <hr/> DATE
---	--------------------------