



HST #837181627

DATE 2015-12-15	TECHNICIAN Darren Mann		JOB/ORDER # 5621		REFERENCE TEXT Client reference				
FIRST NAME Nancy		LAST NAME Richardson	9/						
BILLING ADDRESS COMPANY / BILLING NAME 7-1053 NICOLA ST VANCOUVER, V6G 2E1 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS  7 - 1053 NICOLA ST LINDSAY(DAUGHTER): 778.926.1671 VANCOUVER, V6G 2E1 BRITISH COLUMBIA, CANADA						
PHONE 778-838-0483				EMAIL n.richardson@shaw.ca					

## REASON FOR TODAY'S CALL:

toilet is slowly running tried to fix by replacing a piece but this has not worked bathtub cold water tap is dripping non stop.

## DESCRIPTION OF WORK PERFORMED:

-The toilet FlushValve gasket was warped and the fillvalve would not fully shut off even when the tank was full. I replaced the fillvalve, FlushValve gasket, and supply line. -The seats & springs in the shower valve were warn, I replaced the seats, springs, and lever cover.

QTY.	CODE	DESCRIPTION		UNIT PRICE	PRICE
1		Replace Toilet Fill-Valve, Flapper, Supply - Standard  Replace Delta Seats & Springs		\$169.00	\$169.00
1	11			\$39.00	\$39.00
www.yaletownplumbing.com/feedback [1] WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  Fill in the required details from your		SUBTOTAL:	\$208.00		
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$10.40
		ls from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$218.40

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON MADE THAT SERVICES LISTED ABOVE ARE SATI MATERIALS LISTED HEREON ARE CORRECT. YA SETTLED, RUSTED, DETERIORATION, OR LEAD RESULTING FROM CLEANING OR REPAIRING EXTERMS: NET CASH THE AMOUNTS CONTAINED IN	SFACTORY COMPLETED AND T LETOWN PLUMBING IS NOT RES PIPES, FIXTURES, CLEAN OUTS LISTING FIXTURES OR PIPING.	HAT CHARGES AND SPONSIBLE FOR BROKEN, AND ANY OTHER DAMAGE	s
CHARGES, E. & O. E.	HEREIN ARE FOR LABOUR, MAT	ERIALS AND TRUCK	
		2015-12-15	
CUSTOMER SIGNAT	URE	DATE	