



2015-12-16

DATE

HST #837181627

DATE 2015-12-16	TECHNICIAN Darren Mann		JOB/O 5647	RDER #	REFERENCE TEXT
FIRST NAME Jacq		LAST NAME Wener			
BILLING ADDRESS		100	//	SERVICE ADDRESS	
2222 WEST 13TH AVE VANCOUVER, V6K2S3 BRITISH COLUMBIA, CANADA				2222 WEST 13TH AVE VANCOUVER, V6K2S3 BRITISH COLUMBIA, CANADA	A
PHONE 604.725.7677				EMAIL Jacqueline@renew5.com	

REASON FOR TODAY'S CALL:

Garburator jammed

DESCRIPTION OF WORK PERFORMED:

The garburator grinding chamber was deteriorated and bits of metal were breaking off. I replaced the garburator with a new Waste King 1001 and tested by filling and draning the sink while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00
2	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			
Please visit our feedback page at:		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTEL'	GST (5%):	\$13.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your			TOTAL:	\$292.95
Thank You!		WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BRO SETTLED RUSTED DETERIORATION OF LEAD PIPES FLYTURES CLEAN OUTS AND ANY OTHER DAI	KEN,	

CUSTOMER SIGNATURE