



HST #837181627

DATE 2016-01-04	TECHNICIAN Darren Mann		JOB/ORDER # 5671	REFERENCE TEXT Client reference	
FIRST NAME ben		LAST NAME siepermann			
BILLING ADDRESS COMPANY / BILLING NAME 2175 SALAL DRIVE VANCOUVER, V6K 4V2 BRITISH COLUMBIA, CANADA			#210 - 2175 SALA VANCOUVER, V6I BRITISH COLUME	L DRIVE K 4V2	
PHONE 7783204280			EMAIL bsiepermann@gm	ail.com	

REASON FOR TODAY'S CALL: replace garburator

DESCRIPTION OF WORK PERFORMED:

-I replaced the garburator, basket strainer, and re-piped the ABS drainage. Tested by filling and draining both sides of the sink while running the garburator.

QTY.	CODE	DESCRIPTION			PRICE
1	y	Supply & Install 1/2HP Waste King 1001 Garburator			\$279.00
1	1	Re-Pipe ABS Drainage		\$50.00	\$50.00
		ware	RANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$329.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$16.45
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$345.45
			INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

<u> Thank You!</u>

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT, YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN. SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

 $\underline{\textbf{TERMS}}\text{: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK}$ CHARGES. E. & O. E.