



HST #837181627

DATE 2016-01-05	TECHNICIAN Darren Mann		JOB/ORDER # 5679	REFERENCE TEXT Client reference	
FIRST NAME Linda		LAST NAME Lund			
BILLING ADDRESS COMPANY / BILLING NAME 901 - 977 MAINLAND ST VANCOUVER, V6B1T2 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS  901 - 977 MAINLAND ST, BUZZER 7069 VANCOUVER, V6B1T2 BRITISH COLUMBIA, CANADA		
PHONE 604.689.7921			EMAIL lindaplund@telus.ne	t	

## REASON FOR TODAY'S CALL:

harwood floor behind kitchen sink showing signs of water damage.

## **DESCRIPTION OF WORK PERFORMED:**

-the kitchen faucet was leaking internally, to the underside of the sink, and through the bottom of the cabinet. I replaced the faucet with a new Delta Palo and tested by filling and draining both sides of the sink. -I also removed the dishwasher kick plate and ran it through a quick fill and drain cycle, no moisture was detected under the dishwasher.

QTY.	CODE	DESCRIPTION		UNIT PRICE	PRICE
1		Delta Palo CP - Pull-Out INS	ull-Out INSTALLED		\$319.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback  Fill in the required details from your		: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$319.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$15.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$334.95
		INTERES	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		

RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

Thank You!

invoice and tell us how we did.

CHARGES. E. & O. E. DATE

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK