



DATE 2016-01-11	TECHNICIAN Darren Mann	JOB/ORDER # 5703	REFERENCE TEXT Client reference
FIRST NAME Kalev		LAST NAME Jaaguste	
BILLING ADDRESS COMPANY / BILLING NAME 205 - 33 WEST PENDER VANCOUVER, V6B 0E5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 205 - 33 WEST PENDER VANCOUVER, V6B 0E5 BRITISH COLUMBIA, CANADA	
PHONE 604.518.4691		EMAIL Kalev@kalevfitness.com	

REASON FOR TODAY'S CALL:
 Garburator is broken, its a new unit from last time, but same building so will be the same brand... so check your records and bring one of them with ya)

DESCRIPTION OF WORK PERFORMED:
 The garburator was leaking through cracks in the housing, I replaced the garburator with a new Badger5 and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$299.00	\$299.00
SUBTOTAL:				\$299.00
GST (5%):				\$14.95
TOTAL:				\$313.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2016-01-11

CUSTOMER SIGNATURE

DATE