

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2015-11-16	TECHNICIAN Darren Mann		JOB/ORDER # 5539		REFERENCE TEXT 15-1513	
FIRST NAME Advent		LAST NAME Admin	7			
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 805 - 1033 MARINASIDE CRES BUZ#1359 SHAHAB: 604.346.5536 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.736.6478	-			EMAIL andrea@adventvancouver.com		

REASON FOR TODAY'S CALL:

-toilet running -tenant cannot remove light fixture to change bulb?

DESCRIPTION OF WORK PERFORMED:

-Water was leaking from the left tank bolt. The toilet was installed with the tank pushing up against the back wall with a space between the tank and bowl this made it so that the tank bolts could not be tightened enough. I added rubber spacers and re-tightened the tank bolts, tested and no leaks present. -The light fixture easily pulls out of the ceiling to replace the bulb, then snaps back into place.

QTY.	CODE	DESCRIPTION				UNIT PRICE	PRICE
1	1.	Discount Labour				\$89.00	\$89.00
Guve us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		eedback"	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$89.00		
				LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTE MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT M	GST (5%):	\$4.45	
			INTEREST A	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$93.45	
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. <u>TERMS</u> : NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2015-11-16				
			CUSTOMER SIGNATURE DATE				